

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
DEL,  
1-DOV,  
10-

Dr. Henry Ridgely House  
(Crawford House)  
6 S. State Street  
Dover  
Kent County  
Delaware

DE-177

Documentation: 11 exterior photos (1982)  
1 data page (1983)

Jack E. Boucher, Photographer July, 1982

DE-177-1 EAST FRONT FROM NORTHEAST

DE-177-2 EAST FRONT FROM SOUTHEAST

DE-177-3 EAST FRONT, PORCH

DE-177-4 REAR WING, NORTHWEST CORNER

DE-177-5 NORTH SIDE FROM NORTHWEST

DE-177-6 NORTHWEST CORNER OF HOUSE, DETAIL OF CORNICE

DE-177-7 NORTH SIDE, DETAIL OF SECOND-FLOOR WINDOW

DE-177-8 EAST FRONT, DETAIL OF SECOND-FLOOR WINDOW, CENTER TOWER

DE-177-9 SOUTH SIDE, DETAIL OF BAY WINDOW

DE-177-10 GAZEBO

DE-177-11 PRIVY

HABS  
DEL  
1-DOV,  
10-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to:

Dr. Henry Ridgely House  
6 South State Street  
Dover  
Kent County  
Delaware

HABS No. DE-177

Documentation:

7 interior photos (1983)

David Ames, Photographer

January 1983

DE-177-12 CENTRAL HALLWAY LOOKING NORTH

DE-177-13 FIRST FLOOR, SOUTH FRONT ROOM, LOOKING SOUTHWEST

DE-177-14 DETAIL OF DOOR PANELING, AND DOOR KNOB, FIRST FLOOR FRONT ROOM

DE-177-15 FIREPLACE AND MIRROR ON NORTH WALL OF SOUTH FRONT ROOM

DE-177-16 FIREPLACE NORTH WALL OF SOUTH FRONT ROOM FIRST FLOOR

DE-177-17 FRONT DOOR TO CENTRAL HALLWAY

DE-177-18 DETAIL OF ETCHED GLASS IN FRONT DOOR

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
DEL,  
1-DOV,

ADDENDUM TO:  
DR. HENRY RIDGELY HOUSE  
(CRAWFORD HOUSE)  
6 South State Street  
Dover  
Kent County  
Delaware

HABS No. DE-177 10-

DE-177-1 through DE-177-18 were transmitted to the Library of Congress in 1985.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, July 1982

DE-177-19 (CT) EAST FRONT FROM NORTHEAST

DE-177-20 (CT) EAST FRONT FROM SOUTHEAST